

Sets, Kits, Outfits, and Tools, for Shop Equipment, Automotive Maintenance And Repair: Field Maintenance, Supplemental Set No. 2, Less Power And Shop Equipment, Automotive

SC: 4910-95-A63
NSN: 4910-00-754-0707
LIN: T25756
TM: 9-3405-209-14&P

System Description

Replaced by NSN 4910-01-490-6453 SATS base

This system is not currently in reset.

Reset Type

Reset Work (Field Level) - Work performed to correct equipment faults that are performed at the ORG/DS level; performed by unit level soldiers, augmented by contractor as required.

Reset Strategy

n/a

Reset Procedures

- Replace worn, broken, missing components IAW supply catalog.
- Reorder consumables IAW SC.

Reset Responsibility

Unit

Reset Location

This system is not currently in reset.

- Contact Information -

877.4.PMSKOT (877.476.7568)
rock-pm-skot@conus.army.mil